

F-201 Procedures.

Follow the procedures at PGI F-201 for evidence of required Government contract quality assurance at a subcontractor's facility.

Parent topic: Part 2 -CONTRACT QUALITY ASSURANCE ON SHIPMENTS BETWEEN CONTRACTORS